

TRANEMO

ADVANCED WORKWEAR



EN ISO 11612
A1+A2 B1 C1 F1



EN 61482-2
APC 1

ELIM: 8,1 cal/cm² EBT: 8,7 cal/cm²



EN 1149-5



EN 13034
type PB[6]



EN ISO 20471
CL.3



EN ISO 15797
50 WASHES



TRANEMO SKINSAFE

583181 JAKKE

PFAS-fri¹, metallfri og inherent flammehemmende synbarhetsjakke med to vertikale brystlommer. Jakken er produsert i en meget lett og komfortabel tekstil med høy slitestyrke tilpasset arbeid i energibransjen med krav om beskyttelse mot lysbue.

Skjult glidelås og trykknapper i front. Forlenget ryggparti. To hemper for kommunikasjonsutstyr. Vertikale brystlommer med glidelås. Armlomme med klaff, skjult D-ring og feste for ID-kort. Sidelommer med klaff. Justerbar midjevidde og mansjett. Tre innerlommer der den ene er for mobiltelefon.

Størrelse: XS-4XL

Kvalitet: 811 - Tera TX - 45% modakryl / 35% bomull / 18% polyamid / 2% antistat, 260 g/m²



¹Dette plagget er produsert med ny PFAS-fri tekstil. Vi vil i en tid fremover har blandet lager siden overgangen til PFAS fritt skjer løpende.